

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-1-69S98W /1SWNE

Location ID: 312658



Photo #0305 photo from entrance to location.



Photo #0308 Tank capacity and contents not legible.

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-1-69S98W /1SWNE

Location ID: 312658




Photo #0306 multiple place with weeds on location.



Photo #0310 multiple place with weeds on location.