

Inspection Photos
Location Name: UPV 25-214
Location ID: 329935



Photo #1 Well & Sign



Photo #2 Tank Battery

Inspection Photos
Location Name: UPV 25-214
Location ID: 329935



Photo #3 Separator, ECD & Meter Run.



Photo #4 ECD for production tank.

Inspection Photos
Location Name: UPV 25-214
Location ID: 329935



Photo #5 Trash around methanol system



Photo #6 Trash on south side of tank battery