

Inspection Photos

API: 05-073-06510

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 12/18/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 1. Facing south along the former access road. Vegetation is not establishing along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 2. Facing south along the former access road. Vegetation is not establishing along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 3. Facing south toward the location..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 4. Center of the location facing south. Vegetation is not establishing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 5. Center of the location facing east. Vegetation is not establishing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 6. Center of the location facing north. Vegetation is not establishing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 7. Center of the location facing west. Vegetation is not establishing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 8. Soils seem compacted in areas. Soils need to be evaluated for proper decompaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019

Inspection Photos



Photo 9. Facing east toward the surrounding pasture which consists primarily of Blue grama grassland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06510 | Date: 12/18/2019