

# Inspection Photos

API: 05-073-06412

Operator: UNIT PETROLEUM COMPANY

Inspection Date: 12/19/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019

## Inspection Photos



**Photo 1.** Facing southeast along the reclaimed access road. Vegetation is establishing along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019

## Inspection Photos



**Photo 2.** Facing southeast toward the location. A cattle guard and perimeter fence remain around the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019



## Inspection Photos



**Photo 3.** There is an area with inadequate vegetation establishment at the southwest side of the location. Soils maybe compacted in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019



## Inspection Photos



**Photo 4.** Center of the location facing north. Vegetation is establishing at the location however, there is undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019



## Inspection Photos



**Photo 5.** Center of the location facing east. Vegetation is establishing at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019



## Inspection Photos



**Photo 6.** Center of the location facing west. Vegetation is establishing at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019



## Inspection Photos



**Photo 7.** Center of the location facing south. Vegetation is establishing at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019



## Inspection Photos



**Photo 8.** Facing east toward the surrounding reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06412 | Date: 12/19/2019