

Final Reclamation Inspection

December 19, 2019

Operator: DIVERSIFIED OPERATING CORPORATION - #24461

Location ID: 409384

Inspection Document #: 697500945

Weld County, CO

SESE Section 30 T8N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FEDERAL DODO #30-9-14
Location ID: 409384



Photo 1. Photo taken from the southern access road, facing North. Photo illustrates Operator has performed Final Reclamation activities and that sand bluestem has established throughout the access road.

Inspection Photos
Location Name: FEDERAL DODO #30-9-14
Location ID: 409384



Photo 2. Photo taken from the well location, facing Northeast. See comments under Photo 1.



Photo 3. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: FEDERAL DODO #30-9-14
Location ID: 409384



Photo 4. Reference photo taken east of the location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: FEDERAL DODO #30-9-14
Location ID: 409384



Photo 5. Photo taken from the tank battery location, facing Northeast. Photo illustrates not all equipment has been removed from location.