

Inspection Photos
Location Name: NHF-65N63W /9NENW
Location #: 331576



Photo #1

NHF 21-9 (05-123-20924) Wellsite

Plugged & Abandoned | PA

**NOT Cut & Capped: Temp. cap appears in place
*prior insp.***



Photo #2

NHF 21-9 Wellsite

Plugged & Abandoned | PA

~ 25 yds.

Reclamation progressing

Inspection Photos
Location Name: NHF-65N63W /9NENW
Location #: 331576



Colorado Oil & Gas Conservation Commission
40.42002, -104.44414, 1427.0m, 216°
2019/04/11 03:09:41 PM

Photo #3
NHF 21-9 Battery site
Abandoned
Unused Equipment: Gas meter run & riser
prior insp.



Colorado Oil & Gas Conservation Commission
40.41991, -104.44413, 1429.0m, 217°
12/27/2019 01:58:58 PM

Photo #4
NHF 21-9 Battery site
Abandoned
Unused Equipment
*Gas meter run & riser: **Removed***
Reclamation progressing