

Operator
Sample Date
Lease
Location

Fritzler Resources, Inc.
Oct. 4 2019
Scott 2 (Brown Scott)
Washington County

Remediation Project:

9399

Preliminary Samples	Depth	BTEX mg/KG	DRO(TEPH) mg/Kg	GRO(TVPH) mg/Kg	pH	SAR	Conductance mS/cm	
BRN Sct Comp A	B8456-01	see below	<0.01	26.1	<0.5	8.58	23.8	1.77
BRN Comp 2	B8456-02	see below	<0.01	<10	<0.5	9.8	9.9	0.471
BRN SW	B8456-03	see below	<0.01	11.7	<0.5	8.91	5.6	0.479

Descriptions

BRN Sct Comp A

This sample is a composite of the following locations

- 1 East pit wall adjacent to adjoining pit, 5 ft below top of pit
- 2 Line running approximately in the middle of the bottom of pit

BRN Comp 2

This sample is a composite of the following locations

Line along the south side of pit approximately 5 ft below top of pit

BRN SW

This sample is a composite of the following locations

Line along the southwest corner extending along the west side of pit approximately 5 ft below top of pit