

Inspection Photos
Location Name: Timm PC GK 4-12 TB
Location ID: 461139



Photo 1 – Tank Battery




Photo 2 - NFPA Label on Crude Oil is fading. Produced Water missing capacity label.

Inspection Photos
Location Name: Timm PC GK 4-12 TB
Location ID: 461139



**Photo 3 – NFPA Label on Produced Water tank is fading,
missing capacity label.**