

Interim Reclamation and Stormwater Inspection

December 26, 2019

Operator: CONFLUENCE DJ LLC- #10518

Location ID: 452048

Inspection Document #: 697500961

Weld County, CO

SWSW Section 33 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Freedom /33
Location ID: 452048



Photo 1. Photo taken from the southwestern location, facing North. Photo illustrates Operator has failed to complete Interim Reclamation activities. Northern two wells circled in red.

Inspection Photos
Location Name: Freedom /33
Location ID: 452048



Photo 2. Photo taken from the southwestern location, facing East. See comments under Photo 1. Southern two wells circled in red.

Inspection Photos
Location Name: Freedom /33
Location ID: 452048



Photo 3. Photo taken from the southern location, facing East. Photo illustrates unmanaged weeds along the southern fill slope of location.



Photo 4. Photo taken from the southern location, facing West. See comments under Photo 3.

Inspection Photos
Location Name: Freedom /33
Location ID: 452048



Photo 5. Photo taken from the northern location, facing East. Photo illustrates Operator has failed to prevent the establishment of weeds on the topsoil stockpile.

Inspection Photos
Location Name: Freedom /33
Location ID: 452048



Photo 6. Photo taken from the northern location, facing East. Second photo illustrating Operator has failed to prevent the establishment of weeds on the topsoil stockpile.

Inspection Photos
Location Name: Freedom /33
Location ID: 452048



Photo 7. Photo taken from the northern location, facing North. Photo illustrates an unmanaged noxious thistle.