

Inspection Photos
Location Name: Kiyota 1&2 tank battery
Location ID: 446596



Photo1 TB sign

Photo2 TB

Inspection Photos
Location Name: Kiyota 1&2 tank battery
Location ID: 446596



Photo 3 stained soil under load line valve



Photo 4 Stained soil by load line valve

Inspection Photos
Location Name: Kiyota 1&2 tank battery
Location ID: 446596



Colorado Oil & Gas Conservation Commission
40.09416, -104.83924, 4848.3ft, 130°
12/27/2019 10:23:30

Photo 5 Verticle separators appear to be unused equip.