

**Inspection Photos**  
**Location Name: DF Ranch 17-99HZ**  
**Location ID: 418692**



**Photo 1 – Pumping Unit**



**Photo 2 – Stained Soil**



**Inspection Photos**  
**Location Name: DF Ranch 17-99HZ**  
**Location ID: 418692**



**Photo 3 – Stained Soil at gas engine**