

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 1 –

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 2 – South side of tank battery oil stained soil in berm

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 3 – Northeast corner of tank battery, oil stained soil in berm, oily soil stockpile north of battery berm

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 4 – Oily soil stockpile north of battery berm

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 5 – View southeast at area between tank battery and separator, adjacent to access road to wellhead (north)

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 6 – View north along access road to wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 7 – View east at oily soil cleanup east of wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 8 – View west at oily soil stockpile east of wellhead

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 9 – View northwest at oily soil stockpile east of wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – Chester Kincheloe Tank Battery – Spill
Inspection Date: 12/26/2019



Photo # 10 – View northwest at oily soil stockpile east of wellhead