

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/31/2019

Submitted Date:

12/31/2019

Document Number:

679706747

FIELD INSPECTION FORM

Loc ID 314327 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORTH WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228333	WELL	PA	07/16/2019	GW	103-05170	PICEANCE CREEK UNIT-GOV 5 54-13	PA

General Comment:

[COGCC Inspection Report Summary.](#)

On 12-31-2019, inspector Rick Moran, reviewed the documentation on XTO Energy well Piceance Creek Unit T54- 13G in Rio Blanco county of FIR document 679706460 dated 12-6-2019.

The following compliance issues were resolved:

- 1) No Form 6 Subsequent Report of Abandonment on file. Submit if not already sent.

This is a summary of inspection report 679706747.

Inspected Facilities

Facility ID: 228333 Type: WELL API Number: 103-05170 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____