

Inspection Photos
Operator: Southland Royalty
Location/API #: 007-06184
Date: 12-30-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Location is largely snow covered at this time.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of musk thistles and debris within the eastern project area.



Photo 5. View of reference area, snow covered at this time.