

Inspection Photos
Operator: Southland Royalty
Location/API #: 007-06200
Date: 12-30-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward.



Photo 3. View of the northern project area from the northwestern corner facing eastward. Musk thistles observed growing through snow cover. Perennial grasses such as crested and western wheatgrass were observable.



Photo 4. View of musk thistles within the western project area.



Photo 5. View of reference area, comprised of pinion and juniper woodland.