

Inspection Photos  
Operator: BP America  
Location/API #: 007-06327  
Date: 12-30-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Observable vegetation is a mix of desirable species such as western wheatgrass, and weedy annual species such as cheatgrass and Russian thistle.





Photo 3. View of the southern project area from the southwestern corner facing eastward. Perennial grasses such as crested wheatgrass observed through the snow cover.



Photo 4. View of Canada thistles growing along the eastern edge of the project area.





Photo 5. View of reference area, comprised of pinion and juniper woodland.