

Interim Reclamation Inspection

December 26, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 318460

Inspection Document #: 697500977

Weld County, CO

NWSW Section 18 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: HICKS #13-18 Tank battery

Location ID: 318460



Photo 1. Photo taken from the tank battery location, facing Northeast. Photo illustrates the Operator has failed to control and manage weeds.

Inspection Photos

Location Name: HICKS #13-18 Tank battery

Location ID: 318460



Photo 2. Photo taken from the tank battery location, facing North. See comments under Photo 1.