

# Construction and Stormwater Inspection

December 26, 2019

Operator: VERDAD RESOURCES LLC- #10651

Location ID: 469568

Inspection Document #: 697500981

Weld County, CO

NWSE Section 12 T1N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Safi /1224  
Location ID: 469568



**Photo 1.** Photo taken from the entrance of location, facing North. Photo illustrates Operator has mobilized equipment to the location. Appears a perimeter BMP (ditch) has been installed. Appears weather has delayed construction operations.