

Well Name: Ford Olson 2 **API #** 05-067-08789
Well Name: IGE 128 **API #** 05-067-09568
Well Name: IGE 129 **API #** 05-067-09908
Well Name: IGE 130 **API #** 05-067-09909
Inspection Number: 693900631
Corrective Action: Remove bag and dispose of Musk Thistle.
Action Completed: 8/15/2019

Corrective Action: Stormwater controls installed along the cut slope and along the southern edge of the location.
Sediment controls installed to prevent sediment discharge from discharge points.
Action Completed: 8/16/2019

Corrective Action: Revegetation of interim reclamation areas needs to be conducted within the fall seeding window.
Action Completed: 10/1/2019



