

Piceance Creek Unit F23-18G

API: 05-103-08340

Inspection: 679706755



Photo 1. Location.



Piceance Creek Unit F23-18G

API: 05-103-08340

Inspection: 679706755



Photo 2. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Piceance Creek Unit F23-18G

API: 05-103-08340

Inspection: 679706755



Photo 3. Well head.

Piceance Creek Unit F23-18G

API: 05-103-08340

Inspection: 679706755



Photo 4. Buildings.

Piceance Creek Unit F23-18G

API: 05-103-08340

Inspection: 679706755



39.87666, -108.21238, 7354.3ft, 36°
12/31/2019 11:05:59 AM

Photo 5. Tanks.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Piceance Creek Unit F23-18G

API: 05-103-08340

Inspection: 679706755



Photo 6. Tanks & separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources