

Inspection Photos
Operator: Southland Royalty
Location/API #: 007-06243
Date: 12-30-2019



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the well pad entrance facing westward.



Photo 3. View of the northeastern fill slope from the northeastern edge facing northwestward. Approximately 100 musk thistles observed growing through snow cover.



Photo 4. View of the northern fill slope from the northern edge facing northwestward.



Photo 5. View of reference area, comprised of open grass field, covered in snow at this time.