

Inspection Photos
Operator: Southland Royalty
Location/API #: 007-06183
Date: 12-30-2019



Photo 1. View of the project area from the eastern edge facing center. Kochia debris observable within the foreground.



Photo 2. View of the eastern project area from the northeastern edge facing southward.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of musk thistles observed within the interim reclamation area.



Photo 5. View of reference area, comprised of pinyon and juniper woodland.