

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/02/2020

Submitted Date:

01/02/2020

Document Number:

696101752

FIELD INSPECTION FORM

Loc ID: 306005 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284466	WELL	PR	10/01/2018	GW	123-23816	70 RANCH 13-21	TA

General Comment:

This is WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Shut-down | Inactive.

Centralized Battery serves 2 Location IDs (331508, 306005).
(Well(s): 2: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101750 and/or Location ID #331508 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696101750 and/or Location ID #331508 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type			
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696101750 and/or Location ID #331508 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ Master & casing valves.		

Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696101750 and/or Location ID #331508 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.383103,-104.443722
Comment:	Centralized Battery serves 2 Location IDs (331508, 306005). Refer to Field Inspection Report doc. #696101750 and/or Location ID #331508 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 284466 Type: WELL API Number: 123-23816 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Form 4 Sundry Notice doc. #402171749 indicates TA w/ CIBP date: 10/26/2018.
Approval Pending.
Form 21 doc. #401814624 indicates MIT done: 10/27/2018. Approved.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 01/02/2020 at approximately 12:56 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: 70 RANCH-65N63W /21NWSW Location ID: 306005 Well Name: 70 Ranch 13-21 API: 05-123-23816 Location County: Weld County, Colorado Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Shut-down Inactive.</p> <p>Centralized Battery serves 2 Location IDs (331508, 306005). (Well(s): 2: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696101750 and/or Location ID #331508 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101753	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026606