

# *Inspection Photos*

*Loc#324439*

*Operator: Terra*

*Inspection Number: 692401761*

*Inspection Date: 12/23/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from Entry.

December 23, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra KP Loc#324439



Photo#2:  
Weedy berm to East of entry.



Photo#3:  
Weedy berm to West of entry.

December 23, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra KP Loc#324439





Photo#4:  
Weedy area of pad.



Photo#5:  
Close up of Weedy area of pad.

December 23, 2019




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra KP Loc#324439



Photo#6:  
Weedy berm /slope.




Photo#7:  
Weedy berm /slope.

December 23, 2019





Photo#8:  
Behind Separators.



Photo#9:  
Behind Tanks.

December 23, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra KP Loc#324439