

Inspection Photos

Loc#324234

Operator: Terra

Inspection Number: 692401762

Inspection Date: 12/23/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry.

December 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra McBurney Loc#324234



Photo#2:

View of portion of unstable Cut slope and undercutting of root systems.

December 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra McBurney Loc#324234



Photo#3:
Area behind separator; evidence of slope instability.



Photo#4:
Area behind separator; evidence of slope instability.

December 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra McBurney Loc#324234



Photo#5:
Longview of Cut slope .



Photo#6:
Close up of area identified with arrow in Photo#5.

December 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra McBurney Loc#324234



Photo#7:
View of portion of unstable Cut slope and undercutting of root systems.



Photo#8:
View of portion of unstable Cut slope and undercutting of root systems.

December 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra McBurney Loc#324234



Photo#9:
Desiccated Noxious Weeds on Cut slope area.

December 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra McBurney Loc#324234