

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2020

Submitted Date:

01/02/2020

Document Number:

699500585**FIELD INSPECTION FORM**
 Loc ID: 449521
 Inspector Name: MEDINA, JUSTIN
 On-Site Inspection: ☐
 2A Doc Num:
Operator Information:

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449510	WELL	PR	03/01/2019		123-44330	Ottesen LE 09-368HN	PR
449512	WELL	PR	03/01/2019		123-44332	Ottesen LE 09-363HN	PR
449516	WELL	PR	04/18/2019	OW	123-44335	Ottesen LE 06-290HN	PR
449517	WELL	PR	03/01/2019		123-44336	Ottesen LE 09-366HN	PR
449518	WELL	PR	03/01/2019	LO	123-44337	Ottesen LE 06-311HC	PR
449525	WELL	PR	03/01/2019		123-44343	Ottesen LE 09-368HC	PR
449526	WELL	PR	04/01/2019		123-44344	Ottesen LE 09-365HN	PR
449527	WELL	PR	03/01/2019	OW	123-44345	Ottesen LE 06-311HN	PR
449529	WELL	PR	04/01/2019	OW	123-44347	Ottesen LE 06-351HN	PR
449533	WELL	PR	02/01/2019		123-44351	Ottesen LE 09-365HC	PR
449537	WELL	PR	03/01/2019		123-44355	Ottesen LE 06-370HC	PR
449539	WELL	PR	04/18/2019	OW	123-44357	Ottesen LE 06-290HNX	PR
449546	WELL	PR	03/01/2019		123-44364	Ottesen LE 09-366HNX	PR
449550	WELL	PR	03/01/2019		123-44368	Ottesen LE 09-362HC	PR
458240	WELL	PR	03/01/2019		123-48287	Ottesen LE 06-351HNX	PR
458241	WELL	PR	03/01/2019		123-48288	Ottesen LE 06-370HN	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Red AG fencing		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>449510</u>	Type: <u>WELL</u>	API Number: <u>123-44330</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449512</u>	Type: <u>WELL</u>	API Number: <u>123-44332</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449516</u>	Type: <u>WELL</u>	API Number: <u>123-44335</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449517</u>	Type: <u>WELL</u>	API Number: <u>123-44336</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449518</u>	Type: <u>WELL</u>	API Number: <u>123-44337</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449525</u>	Type: <u>WELL</u>	API Number: <u>123-44343</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449526</u>	Type: <u>WELL</u>	API Number: <u>123-44344</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449527</u>	Type: <u>WELL</u>	API Number: <u>123-44345</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449529</u>	Type: <u>WELL</u>	API Number: <u>123-44347</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449533</u>	Type: <u>WELL</u>	API Number: <u>123-44351</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449537</u>	Type: <u>WELL</u>	API Number: <u>123-44355</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449539</u>	Type: <u>WELL</u>	API Number: <u>123-44357</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449546</u>	Type: <u>WELL</u>	API Number: <u>123-44364</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449550</u>	Type: <u>WELL</u>	API Number: <u>123-44368</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>458240</u>	Type: <u>WELL</u>	API Number: <u>123-48287</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>458241</u>	Type: <u>WELL</u>	API Number: <u>123-48288</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Workover

Comment: At time of inspection rig crew was in process of N/U BOP to perform cleanout operations.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	01/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500586	PICS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026647