

Well Name: Harmon Gas Unit A 2      API #    05-067-07930  
Well Name: IGE 141      API #    05-067-09901  
Inspection Number: 687904515  
Corrective Action: Tires inside secondary containment  
Correction Action Due: 4/18/2019  
Action Completed: 4/22/2019  
Action Taken: Removed tires from secondary containment.

Corrective Action: Repair secondary containment liner  
Correction Action Due: 5/8/2019  
Action Completed: 4/22/2019  
Action Taken: Repaired tears in secondary containment liner

