

Inspection Photos
Location Name: Jack Mleynek #1
Location ID: 318147



Photo 1 WH sign

Photo 2 Dead weeds removed from WH/PU

Inspection Photos
Location Name: Jack Mleynek #1
Location ID: 318147



Photo 3 Dead weeds removed from electric panel area