

HALLIBURTON

iCem[®] Service

SRC ENERGY INC-EBUS

BOST FARM 34C-11-L Production

Sincerely,
Meghan Jacobs

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0	Cementing Job Summary	4
1.1	Executive Summary	4
2.0	Real-Time Job Summary	8
2.1	Job Event Log	8
3.0	Attachments.....	11
3.1	Bost Farm 34C-11-L Production – Job Chart	11

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Bost Farm 34C-11-L cement Production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 78 bbls of spacer were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 359915		Ship To #: 3982037		Quote #:		Sales Order #: 0906074565					
Customer: SRC ENERGY INC-EBUS					Customer Rep:						
Well Name: BOST FARM			Well #: 34C-11-L			API/UWI #: 05-123-50257-00					
Field: WATTENBERG		City (SAP): MILLIKEN		County/Parish: WELD			State: COLORADO				
Legal Description: NW SW-7-5N-66W-2666FSL-1274FWL											
Contractor: PRECISION DRLG					Rig/Platform Name/Num: PRECISION 462						
Job BOM: 7523 7523											
Well Type: HORIZONTAL OIL											
Sales Person: HALAMERICA/HB41307					Srv Supervisor: Lance Carpenter						
Job											
Formation Name											
Formation Depth (MD)		Top			Bottom						
Form Type					BHST						
Job depth MD		18073ft			Job Depth TVD		7070				
Water Depth					Wk Ht Above Floor						
Perforation Depth (MD)		From			To						
Well Data											
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft	
Casing		9.625	8.921	36	LTC	J-55	0	1640			
Casing		5.5	4.778	20	TXP-BTC	P110IC	0	18073			
Open Hole Section			8.5				1640	18093			
Tools and Accessories											
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make		
Guide Shoe	5.5			18073		Top Plug	5.5	1	HES		
Float Shoe	5.5					Bottom Plug	5.5	1	HES		
Float Collar	5.5			18025		SSR plug set	5.5		HES		
Insert Float	5.5			17966		Plug Container	5.5		HES		
Stage Tool	5.5					Centralizers	5.5		HES		
Fluid Data											
Stage/Plug #: 1											
Fluid #	Stage Type	Fluid Name			Qty	Qty UoM	Mixing Density lbm/gal	Yield ft/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal

1	Tuned Prime Cement Spacer Base - RKS/SE	TUNED PRIME CEMENT SPACER SYS	80	bbbl	12.5	2.72			
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	ElastiCem	ELASTICEM (TM) SYSTEM	1281	sack	13.2	1.57		8	7.52
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	NeoCem	NeoCem TM	1117	sack	13.2	2.04		8	9.79
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
4	MMCR Displacement	MMCR Displacement	200	bbbl	8.34			8	
0.20 gal/bbl		MICRO MATRIX CEMENT RETARDER, 5 GAL PAIL (100003781)							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
5	Water	Water	308	bbbl	8.33			8	
1 gal/Mgal		CLA-WEB - TOTE (101985045)							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
6	MMCR Displacement	MMCR Displacement	70	bbbl	8.34			8	
0.20 gal/bbl		MICRO MATRIX CEMENT RETARDER, 5 GAL PAIL (100003781)							
Cement Left In Pipe		Amount	107 ft			Reason			Shoe Joint
Mix Water:		pH 7	Mix Water Chloride: 500 ppm			Mix Water Temperature: 64 °F			
Cement Temperature:		## °F °C	Plug Displaced by: 8.4 lb/gal Water			Disp. Temperature: ## °F °C			
Plug Bumped?:		Yes	Bump Pressure: 2700 psi			Floats Held? Yes			
Cement Returns:		## bbl m3	Returns Density: ## lb/gal kg/m3			Returns Temperature: ## °F °C			

Comment

JOB WENT WELL. NO ACCIDENT, INJURY OR SPILL. JOB PERFORMED AS DESIGNED. BOTTOM PLUG DROPPED BEFORE SPACER. ALL SLURRIES VERIFIED BY PRESSURIZED MUD BALANCE AND MIX WATER. DOWNHOLE DENSITY NOT READING CORRECTLY SO CHART INCLUDES RECIRCULATION (MIX) DENSITY. TOP PLUG DROPPED BEFORE DISPLACEMENT. DISPLACED WITH 398 BBL WATER UNEXPECTEDLY LOSING RETURNS AND SURFACE PRESSURE DROP 3 TIMES BUT WERE ABLE TO REGAIN THEM EACH TIME. BUMPED PLUG AT 3 BPM AT 2700 PSI, TOOK TO 3150 PSI AND HELD FOR 10 MINUTES. PRESSURED UP TO 4950 PSI TO OPEN WET SHOE SUB THEN PUMPED 6 BBL WET SHOE. BLED OFF PRESSURE, FLOATS HELD, 2 BBL BACK. 78 BBL SPACER TO SURFACE.

TOP OF CEMENT – 45'

TOP OF SPACER – SURFACE WITH 78 BBL BACK

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press <i>(psi)</i>	DH Density <i>(ppg)</i>	Comb Pump Rate <i>(bbl/min)</i>	Comments
Event	1	Comment	Call Out	11/3/2019	23:00:00	USER				CREW CALLED OUT. ON LOCATION TIME 0500
Event	2	Depart Shop for Location	Depart Shop for Location	11/4/2019	03:00:00	USER				CREW HAS VERIFIED EQUIPMENT AND MATERIALS FOR JOB. CREW HAS JOURNEY MANAGEMENT SAFETY MEETING DISCUSSING ROUTES, STOPS, CONVOR ORDER, FOLLOWING DISTANCE, DRIVING TO CONDITIONS, TRAFFIC AND THEN DEPART FOR LOCATION
Event	3	Arrive At Loc	Arrive At Loc	11/4/2019	04:00:00	USER				CREW ARRIVES AT LOCATION. RIG RIH CASING 16000'. CREW HAS SITE ASSESSMENT SAFETY MEETING DISCUSSING LOCATION HAZARDS AND PRE RIG UP SAFETY MEETING DISCUSSING OPERATIONS, RED ZONES, MUSTER AREAS, PINCH POINTS, LINE OF FIRE, EQUIPMENT LAYOUT, SLIPS TRIPS FALLS, SPILLS AND BEGIN RIGGING UP
Event	4	Casing on Bottom	Casing on Bottom	11/4/2019	06:00:00	USER				CASING ON BOTTOM. RIG BEGINS FILLING CASING THROUGH CRT AND RIGGING DOWN CASING CREW
Event	5	Safety Meeting	Safety Meeting	11/4/2019	08:00:00	USER	56.00	0.78	0.00	CREW, RIG CREW AND CUSTOMER REP HAVE PRE JOB SAFETY MEETING DISCUSSING HAZARDS, RED ZONES, MUSTER AREAS, STOP WORK, LIFTING OPERATIONS, COMMANDER HEAD SPECIFIC HAZARDS, COMMUNICATION, SLIPS TRIPS FALLS, HAND PLACEMENT, LINE OF FIRE AND THE JOB PROCEEDURE
Event	6	Start Job	Start Job	11/4/2019	09:28:38	COM6	41.00	6.95	0.00	START JOB
Event	7	Test Lines	Test Lines	11/4/2019	09:48:29	COM6	3850.00	8.27	0.00	FILL HES LINES WITH 3 BBL AND PRESSURE TEST TO 6500 PSI. HELD TEST FOR A FEW MINUTES TO ENSURE NO LEAKS. TEST GOOD
Event	8	Drop Bottom Plug	Drop Bottom Plug	11/4/2019	09:53:03	USER	153.00	8.31	0.00	DROP BOTTOM PLUG
Event	9	Pump Spacer 1	Pump Spacer 1	11/4/2019	09:54:18	COM6	150.00	8.30	0.00	PUMP 80 BBL TUNED PRIME SPACER 12.5# 2.72 YIELD 16 GAL

Event	10	Pump Lead Cement	Pump Lead Cement	11/4/2019	10:13:42	COM6	155.00	11.54	4.00	PUMP 358 BBL ELASTICEM LEAD 13.2# 1.57 YIELD 7.52 GAL 1281 SACKS
Event	11	Pump Tail Cement	Pump Tail Cement	11/4/2019	11:02:41	USER	651.00	11.99	8.00	PUMP 406 BBL NEOCEM TAIL 13.2# 2.04 YIELD 9.79 GAL 1117 SACKS
Event	12	Shutdown	Shutdown	11/4/2019	11:58:15	COM6	43.00	12.09	0.00	SHUTDOWN. WASH PUMPS AND LINES TO THE PIT
Event	13	Drop Top Plug	Drop Top Plug	11/4/2019	12:06:40	COM6	29.00	8.48	0.00	DROP TOP PLUG
Event	14	Pump Displacement	Pump Displacement	11/4/2019	12:07:49	COM6	16.00	8.33	0.00	PUMP 398 BBL WATER DISPLACEMENT WITH FIRST 20 BBL MMCR, LAST 70 BBL MMCR AND CLAYWEB THROUGHOUT
Event	15	Comment	Comment	11/4/2019	12:48:24	USER	2931.00	8.33	5.40	PUMPING DISPLACEMENT AND SUDDENLY LOST PRESSURE AS WELL AS RETURNS. SLOWED RATE UNTIL PRESSURE LEVELED OUT AND WE WERE ABLE TO BUILD LIFT PRESSURE AGAIN AND RETURNS CAME BACK
Event	16	Comment	Comment	11/4/2019	13:03:51	USER	2727.00	8.33	4.00	PRESSURE DROPPED AGAIN RAPIDLY AND RETURNS WERE LOST. AGAIN CREW WAS ABLE TO CONTROL DROP WITH RATE AND BEGIN LIFTING ONCE MORE AS RETURNS CAME BACK
Event	17	Comment	Comment	11/4/2019	13:12:37	USER	2614.00	8.32	3.50	PRESSURE DROPPED AGAIN COMBINED WITH RETURNS STOPPING. RATE WAS ADJUSTED TO CONTROL DROP AND ONCE MORE ESTABLISH CIRCULATION
Event	18	Bump Plug	Bump Plug	11/4/2019	13:23:44	COM6	3115.00	8.32	0.00	BUMPED PLUG. FINAL CIRCULATING PRESSURE 2700 PSI. TOOK TO 3100 PSI AND HELD FOR 10 MINUTES
Event	19	Comment	Comment	11/4/2019	13:31:16	USER	3294.00	8.32	0.90	PRESSURE UP TO 4950 PSI TO OPEN WET SHOE SUB THEN PUMPED 6 BBL WET SHOE. FULL RETURNS ONCE WET SHOE OPENED
Event	20	Check Floats	Check Floats	11/4/2019	13:34:57	USER	1705.00	8.31	0.00	BLED OFF PRESSURE, FLOATS HELD, 2 BBL BACK
Event	21	End Job	End Job	11/4/2019	13:36:37	COM6	19.00	8.30	0.00	END JOB
Event	22	Safety Meeting	Safety Meeting	11/4/2019	13:40:00	USER	15.00	8.30	0.00	CREW HAS PRE RIG DOWN SAFETY MEETING DISCUSSING SLIPS TRIPS FALLS, LIFTING OPERATIONS, LINE OF FIRE, TEAM LIFTING, PROPER PPE, COMMUNICATION AND BEGIN RIGGING DOWN EQUIPMENT
Event	23	Depart Location	Depart Location	11/4/2019	16:00:00	USER				CREW IS RIGGED DOWN AND READY TO DEPART. CREW HAS JOURNEY MANAGEMENT SAFETY MEETING

DISCUSSING HOURS OF SERVICE, FIT FOR DUTY,
DIRECTIONS, CONVOY ORDER, FOLLOWING DISTANCE,
WALK AROUNDS AND DEPART FROM LOCATION

3.0 Attachments

3.1 Bost Farm 34C-11-L Production – Job Chart

