

**Inspection Photos**  
**Location Name: Castor 1-36-11-9-59 PAD**  
**Location ID: 427480**




**Photo 1 – Tank Battery**



**Photo 2 – Wellheads**



**Inspection Photos**  
**Location Name: Castor 1-36-11-9-59 PAD**  
**Location ID: 427480**



**Photo 3 – Stained Soil at Gas Lift Compressor**



**Photo 4 – No Wildlife netting on Secondary Containment**

