

Inspection Photos
Location Name: Jack Mleynek #3
Location ID: 336296



Photo 1 WH sign

Photo 2 WH/PU

Inspection Photos
Location Name: Jack Mleynek #3
Location ID: 336296



Photo 3 Oil stain on cement and soil has been cleaned and removed

Photo 4 PU gear box appears to have been tightened