

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/03/2020

Submitted Date:

01/03/2020

Document Number:

696301056

**FIELD INSPECTION FORM**
 Loc ID 422413 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email                                  | Comment |
|--------------|-------|--|---------|
| Kraich, Adam |       | adam.kraich@state.co.us                |         |
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 422377      | WELL | PR     | 10/02/2012  | OW         | 123-33238 | CASTOR LC 27-72HN | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | Panels   |       |  |
| Corrective Action: |          | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Compressor                  | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: VRU                         | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Emission Control Device     | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bradenhead                  | # 1 |       |                 |

|                       |                                  |  |       |  |
|-----------------------|----------------------------------|--|-------|--|
| Comment:              | Appears to be plumbed to surface |  | Date: |  |
| Corrective Action:    |                                  |  | Date: |  |
| Type: Bird Protectors | # 3                              |  |       |  |
| Comment:              |                                  |  | Date: |  |
| Corrective Action:    |                                  |  | Date: |  |
| Type: Gas Meter Run   | # 2                              |  |       |  |
| Comment:              |                                  |  | Date: |  |
| Corrective Action:    |                                  |  | Date: |  |
| Type: Plunger Lift    | # 1                              |  |       |  |
| Comment:              |                                  |  | Date: |  |
| Corrective Action:    |                                  |  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type        | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | BV CONCRETE |         | ,      |
| Comment:           |   |          |             |         |        |
| Corrective Action: |   |          |             |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 60 BBLS  |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                         | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------------------|---------------------|---------------------|-------------|
|                    |                                  |                     |                     |             |
| Comment:           | Shares berm with Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                  |                     |                     | Date:       |

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 300 BBLS | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

|                    |          |                     |                     |             |                       |       |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|-------|
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS                |       |
| CRUDE OIL          | 5        | 300 BBLs            | STEEL AST           |             | 40.715430,-103.954890 |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Paint</b>       |          |                     |                     |             |                       |       |
| Condition          | Adequate |                     |                     |             |                       |       |
| Other (Content)    |          |                     |                     |             |                       |       |
| Other (Capacity)   |          |                     |                     |             |                       |       |
| Other (Type)       |          |                     |                     |             |                       |       |
| <b>Berms</b>       |          |                     |                     |             |                       |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Venting:</b>    |          |                     |                     |             |                       |       |
| Yes/No             |          |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Flaring:</b>    |          |                     |                     |             |                       |       |
| Type               |          |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 422377 | Type: | WELL | API Number: | 123-33238 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |       |      |             |           |         |    |               |    |
| Comment:             |        | PR    |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <a href="#">Routine Inspection. Snow covered ground in some spots at the time of Inspection.</a> | petrie | 01/03/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696301057    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5028458">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5028458</a> |