



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 13, 2019 8:49:20 AM MST
Server Receive Date:	Dec 13, 2019 8:49:26 AM MST
Reference Number:	20191213-18126250003
Location:	15731 US-550, Bloomfield, NM 87413, USA Dec 13, 2019 8:33:44 AM MST [ <a href="#">View Map</a> ]

## Information

Name	l.guerrero@kosinm.com
Date	Sep 11, 2019
Well Name	LOS PINOS SWD
API Number	50670697300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Install Rock Run Down Removed sediment from BMP's Cleaned ditch

Photo of first corrective action completed



Completed work description Corrective Action 1

Rock rundowns re/established

Photo of second corrective action completed



Completed work description of corrective action 2  
Completed work description of corrective action 3  
Completed work description of corrective action 4  
Summary of all work completed

Berm re established around entire pad

.  
.

Installed new rock rundown as needed. Created diversion ditch and berms to establish proper water flow around edge of pad. Check all signs and other punch list items as needed.