




## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Cole Nichols (colen@horizonenvservices.com)  
Submission Date: Sep 24, 2019 1:06:53 PM MDT  
Server Receive Date: Sep 24, 2019 1:08:45 PM MDT  
Reference Number: 20190924-18118297068  
Location: 557 Airpark Dr, Durango, CO 81303, USA  
Sep 24, 2019 1:08:11 PM MDT [ [View Map](#) ]

## Information

Name colen@horizonenvservices.com  
Date Sep 18, 2019  
Well Name LOS PINOS WATER DISPOSAL WELL METER 1  
API Number 50670697300  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated noxious weeds in reclamation area

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

treated noxious weeds



Completed work description  
 Completed work description of corrective action 4  
 Summary of all work completed

treated noxious weeds  
 treated noxious weeds in reclamation area  
 treated noxious weeds in reclamation area