



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 13, 2019 8:33:46 AM MST
Server Receive Date:	Dec 13, 2019 8:33:51 AM MST
Reference Number:	20191213-18126247625
Location:	15731 US-550, Bloomfield, NM 87413, USA Dec 13, 2019 8:33:44 AM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Sep 26, 2019
Well Name	PAYNE, EVELYN GAS UNIT C 1
API Number	50670690400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Erosion Repairs Install Rock Run Down Clean up Operator Debris Grading of Well Pad

Photo of first corrective action completed



Completed work description Corrective Action 1

Well sign

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



Completed work description of corrective action 3

Completed work description of corrective action 4

Summary of all work completed

Repaired BMP and installed rock rundown

Repaired diversion ditch

.

Established silt traps with rock run downs. Cleaned and Bermed up ditch. Repaired BMP's and removed wattles. Removed all trash and debris. Checked all signage.