



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Dec 13, 2019 12:38:23 PM MST
Server Receive Date:	Dec 13, 2019 12:40:41 PM MST
Reference Number:	20191213-18126271207
Location:	557 Airpark Dr, Durango, CO 81303, USA Dec 13, 2019 12:38:17 PM MST [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Dec 11, 2019
Well Name	WIRT GAS UNIT C MV 1
API Number	50670527400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Removed broken sign.

Photo of second corrective action completed



Completed work description of corrective action 2

Removed additional debris.

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

Removed broken sign.



Completed work description  
 Completed work description of corrective action 4  
 Additional photos

Removed additional debris.  
 Removed additional debris.



Additional photos



Completed work description  
Summary of all work completed

Removed debris off location.  
Removed debris off location.