

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/06/2020

Submitted Date:

01/06/2020

Document Number:

679706828

FIELD INSPECTION FORM

Loc ID 335980	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 14 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296053	WELL	PR	06/30/2010	GW	103-11278	FEDERAL RG 14-14-298	PR
296054	WELL	PR	10/28/2010	GW	103-11277	FEDERAL RG 24-14-298	PR
296056	WELL	PR	10/19/2010	GW	103-11275	FEDERAL RG 34-14-298	PR
426127	WELL	PR	01/31/2014	GW	103-11895	Federal RG 331-23-298	PR
426129	WELL	PR	01/31/2014	GW	103-11896	Federal RG 534-14-298	PR
426130	WELL	PR	08/24/2018	GW	103-11897	Federal RG 414-14-298	PR
426131	WELL	PR	09/24/2012	GW	103-11898	Federal RG 321-23-298	PR
426134	WELL	PR	01/31/2014	GW	103-11899	Federal RG 521-23-298	PR
426136	WELL	PR	01/28/2014	GW	103-11900	Federal RG 411-23-298	PR
426137	WELL	SI	03/01/2019	GW	103-11901	Federal RG 531-23-298	SI
426138	WELL	PR	09/24/2012	GW	103-11902	Federal RG 11-23-298	PR
426139	WELL	PR	01/28/2014	GW	103-11903	Federal RG 434-14-298	PR
426142	WELL	PR	06/13/2018	GW	103-11904	Federal RG 524-14-298	PR

General Comment:

COGCC Inspection Report Summary.

On 1-6-2020, inspector Rick Moran, reviewed the documentation on TEP well Federal RG 411-23-298 in Rio Blanco county of FIR document 679706430 dated 12-4-2019.

The following compliance issues were resolved:

- 1) Submit Form 4 with correct well latitude & longitude for well RG 411-23-298 (05-103-11900).

This is a summary of inspection report 679706828.

Inspected Facilities									
Facility ID:	296053	Type:	WELL	API Number:	103-11278	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296054	Type:	WELL	API Number:	103-11277	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296056	Type:	WELL	API Number:	103-11275	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	426127	Type:	WELL	API Number:	103-11895	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	426129	Type:	WELL	API Number:	103-11896	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	426130	Type:	WELL	API Number:	103-11897	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	426131	Type:	WELL	API Number:	103-11898	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	426134	Type:	WELL	API Number:	103-11899	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	426136	Type:	WELL	API Number:	103-11900	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Form 4 document 402260005 received 1-2-2020 with corrected well coordinated.](#)

Corrective Action:

Date:

Facility ID:	426137	Type:	WELL	API Number:	103-11901	Status:	SI	Insp. Status:	SI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: [Last recorded production January 2019.](#)

Corrective Action:

Date: _____

Facility ID:	426138	Type:	WELL	API Number:	103-11902	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [PR](#)

Corrective Action:

Date:

Facility ID:	426139	Type:	WELL	API Number:	103-11903	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [PR](#)

Corrective Action:

Date:

Facility ID:	426142	Type:	WELL	API Number:	103-11904	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [PR](#)

Corrective Action:

Date: