



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Dec 13, 2019 1:30:36 PM MST
Server Receive Date:	Dec 13, 2019 1:32:54 PM MST
Reference Number:	20191213-18126279016
Location:	557 Airpark Dr, Durango, CO 81303, USA Dec 13, 2019 1:30:04 PM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Dec 12, 2019
Well Name	SHARP, MF GAS UNIT A 1
API Number	50670726600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

before removal

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

after removal



Completed work description
 Completed work description of corrective action 4

before removal
 mowed and removed weed debris from around equipment

Additional photos



Additional photos



Additional photos



Completed work description

Summary of all work completed

mowed and removed weed debris from around
equipment- no spray along entrance road
initial treatment on 4/4/19