



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 13, 2019 3:32:44 PM MST
Server Receive Date:	Dec 13, 2019 3:32:56 PM MST
Reference Number:	20191213-18126294141
Location:	9 Rd 3227, Aztec, NM 87410, USA Dec 13, 2019 3:32:11 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Sep 18, 2019
Well Name	DAVIS, FRANK GAS UNIT A 1
API Number	50670752600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Grading/recontour Erosion Repairs Install Rock Run Down Spot seeding

Photo of first corrective action completed



Completed work description Corrective Action 1

Rebuilt berm to capacity

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



Seeded around the southeastern project area

Completed work description of corrective action 3

Photo of fourth corrective action completed



Re established berm around equipment.

Completed work description

Completed work description of corrective action 4

Summary of all work completed

Built rock run down

.

Fixed all erosion issues. Cleaned up trash and debris. Checked signage and rig anchors. Seeded around the southeastern project area