



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Cole Nichols (colen@horizonenvservices.com) |
| Submission Date: | Dec 17, 2019 4:59:48 PM MST |
| Server Receive Date: | Dec 17, 2019 5:02:11 PM MST |
| Reference Number: | 20191218-18126782766 |
| Location: | 557 Airpark Dr, Durango, CO 81303, USA Dec 17, 2019 5:01:23 PM MST [View Map] |

Information

| | |
|-----------------|------------------------------|
| Name | colen@horizonenvservices.com |
| Date | Dec 17, 2019 |
| Well Name | BELLINO GAS UNIT 1 |
| API Number | 50670697400 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Clean up Operator Debris |

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up operator debris.

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up operator debris.

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed

Cleaned up operator debris.



Completed work description
Completed work description of corrective action 4
Additional photos

Cleaned up operator debris.
Cleaned up operator debris.



Additional photos



Additional photos



Additional photos



Additional photos



Completed work description

Cleaned up operator debris on Bellino #1 & #3.

Summary of all work completed

Cleaned up operator debris on Bellino #1 & #3.