

Inspection Photos
Location Name: DF Ranch 9-42
Location ID: 410114




Photo 1 – Pumping Units



Photo 2 – Well head Sign



Inspection Photos
Location Name: DF Ranch 9-42
Location ID: 410114




Photo 3 – Stained Soil at Gas Engine



Photo 4 – Stained Soil at Gas Engine

