

Final Reclamation Inspection

January 2, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 307226

Inspection Document #: 697500992

Weld County, CO

SESE Section 1 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: JACKSON #44-1U
Location ID: 307226



Photo 1. Photo taken from the eastern access road, facing West. Photo illustrates it appears the Operator has performed final reclamation activities with the evidence of straw crimped mulch. Note: snow cover prevented COGCC staff from performing a complete assessment.

Inspection Photos
Location Name: JACKSON #44-1U
Location ID: 307226



Photo 2. Photo taken north of the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: JACKSON #44-1U
Location ID: 307226



Photo 3. Photo taken from the east tank battery location, facing West. See comments under Photo 1.