

# Final Reclamation Inspection

January 2, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 307227

Inspection Document #: 697500994

Weld County, CO

SESE Section 1 T5N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: JACKSON #1-DU  
Location ID: 307227



**Photo 1.** Photo taken from the eastern access road, facing West. Photo illustrates it appears the Operator has performed final reclamation activities with the evidence of straw crimped mulch. Note: snow cover prevented COGCC staff from performing a complete assessment.

Inspection Photos  
Location Name: JACKSON #1-DU  
Location ID: 307227



**Photo 2.** Photo taken from the east tank battery/ well location, facing West. See comments under Photo 1.