

Final Reclamation Inspection

January 2, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 307225

Inspection Document #: 697500996

Weld County, CO

SWSE Section 1 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: JACKSON #34-1U
Location ID: 307225



Photo 1. Photo taken from the eastern access road, facing West. Photo illustrates it appears the Operator has performed final reclamation activities with the evidence of straw crimped mulch. Note: snow cover prevented COGCC staff from performing a complete assessment.

Inspection Photos
Location Name: JACKSON #34-1U
Location ID: 307225



Photo 2. Photo taken from the east tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: JACKSON #34-1U
Location ID: 307225



Photo 3. Photo taken from the west tank battery location, facing West towards the western access road and well location. See comments under Photo 1.