



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Dec 23, 2019 2:27:33 PM MST
Server Receive Date:	Dec 23, 2019 2:29:53 PM MST
Reference Number:	20191223-18127517486
Location:	557 Airpark Dr, Durango, CO 81303, USA Dec 23, 2019 2:29:04 PM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Dec 17, 2019
Well Name	DEKAY GAS UNIT A 1
Location Name (Other)	dekay A3
API Number	50670700000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Erosion Repairs Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



removed weed debris

Completed work description of corrective action 3

Photo of fourth corrective action completed



removed weed debris

Completed work description

Completed work description of corrective action 4

Additional photos



sediment removal

removed weed debris and sediment

Additional photos



Completed work description
Summary of all work completed

removed weed debris and sediment
initial treatment on 4/18/19