



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Dec 23, 2019 3:43:53 PM MST
Server Receive Date: Dec 23, 2019 3:46:12 PM MST
Reference Number: 20191223-18127531421
Location: 557 Airpark Dr, Durango, CO 81303, USA
Dec 23, 2019 3:43:07 PM MST [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Dec 23, 2019
Well Name MILLER FEDERAL GAS UNIT 1
API Number 50670713900
Select State Colorado
Work type COGCC Inspection AR
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

before removal

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

after removal



Completed work description
 Completed work description of corrective action 4
 Additional photos

before removal
 removed weed debris



Additional photos



Completed work description
Summary of all work completed

removed weed debris from reclamation area
initial treatment on 6/25/19