



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 23, 2019 9:46:21 PM MST
Server Receive Date:	Dec 23, 2019 9:46:27 PM MST
Reference Number:	20191224-18127554630
Location:	13 Road 51921, Bloomfield, NM 87413, USA Dec 23, 2019 9:37:47 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Dec 23, 2019
Location Name (Other)	Carmelita Gallegos A 3
Location API (Other)	0500706325
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions

Photo of first corrective action completed



Completed work description Corrective Action 1

Removed pumping unit.

Photo of second corrective action completed



Completed work description of corrective action 2

Repaired diversion ditch on southern side of pad.

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

Repaired diversion ditch on eastern side of pad.



Completed work description of corrective action 4
 Summary of all work completed

Removed unused equipment, repaired diversion ditches, cleaned up stained soil around wellhead and picked up all trash and debris.