



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 26, 2019 5:51:27 PM MST
Server Receive Date:	Dec 26, 2019 5:51:33 PM MST
Reference Number:	20191227-18127822565
Location:	15731 US-550, Bloomfield, NM 87413, USA Dec 26, 2019 5:51:20 PM MST [ <a href="#">View Map</a> ]

Information

Name	l.guerrero@kosinm.com
Date	Dec 23, 2019
Well Name	BONDS GAS UNIT 1
API Number	50670578700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed



Completed work description of corrective action 2

Created diversion ditch to divert storm water into rock armored run down and to prevent erosional rilling.

Photo of third corrective action completed



Completed work description of corrective action 3

Diverted storm water into rock armored run down.

Photo of fourth corrective action completed



Completed work description of corrective action 4

Installed silt trap with rock armored run downs on erosion channel.

Additional photos



Summary of all work completed

Installed diversion ditches and berms to divert storm water into rock armored run downs. Replaced BGT sign.