

Final Reclamation Inspection

January 2, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 332988

Inspection Document #: 697500998

Weld County, CO

SESW Section 6 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 1. Photo taken from the access road, facing North. Photo illustrates a pipeline may have been installed along the former access road.

COGCC staff did not inspect the well/tank battery location due to locked gates. Staff did not feel comfortable walking onto property without permission.

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 2. Google Earth aerial imagery taken 10/14/2017 during active operations, illustrating the total disturbance area.

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 3. Google Earth aerial imagery taken 7/17/2019 after plugging operations, illustrating it appears the Operator has performed final reclamation activities.