

Final Reclamation Inspection

January 2, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 333250

Inspection Document #: 697501000

Weld County, CO

NENE Section 6 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LIND-65N67W 6NENE
Location ID: 333250



Photo 1. Photo taken from the entrance of location, facing West. Photo illustrates Operator has performed final reclamation activities with the evidence of straw crimped mulch and drill rows.

Inspection Photos
Location Name: LIND-65N67W 6NENE
Location ID: 333250



Photo 2. Photo taken from the eastern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: LIND-65N67W 6NENE
Location ID: 333250



Photo 3. Photo taken from the eastern location, facing West. See comments under Photo 1.